



ТАБЛИЦА КООРДИНАТ УСТАНОВЛЕННЫХ КРАСНЫХ ЛИНИЙ

Координаты Красных Линий			
Часть 2			
№	X	Y	№
1	429346.2801	1303936.0829	1
2	429378.5800	1303998.1700	2
3	429472.7200	1304179.1500	3
4	429499.5700	1304230.7500	4
5	429519.5582	1304270.3187	5
6	429509.8625	1304303.5225	6
7	429465.9977	1304364.0513	7
8	429451.3100	1304406.6400	8
9	429447.3900	1304417.9900	9
10	429441.0700	1304436.1900	10
11	429429.6700	1304469.2400	11
12	429422.6500	1304489.3600	12
13	429402.8753	1304546.3925	13
14	429397.4000	1304560.3600	14
15	429394.6500	1304588.0300	15
16	429385.1500	1304616.5600	16
17	429377.0524	1304627.2157	17
18	429371.9100	1304656.4800	18
19	429364.1300	1304659.7400	19
20	429271.5016	1304694.5004	20
21	429226.8427	1304684.6470	21
22	429064.5246	1304846.5323	22
23	429047.5753	1304856.2868	23
24	429028.6221	1304848.0151	24
25	429014.1600	1304800.8400	25
26	429003.6000	1304766.1100	26
27	428994.3528	1304735.7170	27
28	428989.6300	1304720.2200	28
29	428984.7420	1304703.5974	29
30	428982.0100	1304630.3200	30
31	428958.1500	1304613.1100	31
32	428948.0100	1304578.6200	32
33	428944.4244	1304566.4716	33
34	428937.8800	1304522.1500	34
35	428935.9861	1304481.2312	35
36	428935.0800	1304513.0500	36
37	428925.0100	1304506.8200	37
38	428924.7200	1304500.5400	38
39	428922.5491	1304497.5491	39
40	428921.3160	1304493.3160	40
41	428919.3442	1304393.7331	41
42	428912.4421	1304391.8535	42
43	428905.0600	1304396.1816	43
44	428904.3861	1304395.6129	44
45	428903.5455	1304397.5455	45
46	428902.0100	1304397.0100	46
47	428901.0111	1304397.0111	47
48	428900.3800	1304397.0100	48
49	428899.2100	1304397.0100	49
50	428898.1578	1304404.8000	50
51	428897.8561	1304405.0765	51
52	428897.7899	1304404.8000	52
53	428897.7000	1304403.9400	53
54	428897.5700	1304402.9400	54
55	428897.4200	1304401.7800	55
56	428897.2500	1304401.5200	56
57	428897.0700	1304401.2600	57
58	428896.8800	1304401.0000	58
59	428896.6900	1304400.7400	59
60	428896.5000	1304400.4800	60
61	428896.3100	1304400.2200	61
62	428896.1200	1304400.0000	62
63	428895.9300	1304399.7400	63
64	428895.7400	1304399.4800	64
65	428895.5500	1304399.2200	65
66	428895.3600	1304398.9600	66

Координаты Красных Линий			
Часть 3			
№	X	Y	№
1	428757.1436	1304113.3878	1
2	428756.5409	1304213.0600	2
3	428757.2300	1304255.1400	3
4	428755.0392	1304451.3190	4
5	428755.0392	1304463.0851	5
6	428755.0392	1304485.8611	6
7	428755.0392	1304511.3900	7
8	428755.0392	1304536.7964	8
9	428755.0392	1304562.3028	9
10	428755.0392	1304587.8092	10
11	428755.0392	1304613.3156	11
12	428755.0392	1304638.8220	12
13	428755.0392	1304664.3284	13
14	428755.0392	1304689.8348	14
15	428755.0392	1304715.3412	15
16	428755.0392	1304740.8476	16
17	428755.0392	1304766.3540	17
18	428755.0392	1304791.8604	18
19	428755.0392	1304817.3668	19
20	428755.0392	1304842.8732	20
21	428755.0392	1304868.3796	21
22	428755.0392	1304893.8860	22
23	428755.0392	1304919.3924	23
24	428755.0392	1304944.8988	24
25	428755.0392	1304970.4052	25
26	428755.0392	1305000.0000	26
27	428755.0392	1305030.0000	27
28	428755.0392	1305060.0000	28
29	428755.0392	1305090.0000	29
30	428755.0392	1305120.0000	30
31	428755.0392	1305150.0000	31
32	428755.0392	1305180.0000	32
33	428755.0392	1305210.0000	33
34	428755.0392	1305240.0000	34
35	428755.0392	1305270.0000	35
36	428755.0392	1305300.0000	36
37	428755.0392	1305330.0000	37
38	428755.0392	1305360.0000	38
39	428755.0392	1305390.0000	39
40	428755.0392	1305420.0000	40
41	428755.0392	1305450.0000	41
42	428755.0392	1305480.0000	42
43	428755.0392	1305510.0000	43
44	428755.0392	1305540.0000	44
45	428755.0392	1305570.0000	45
46	428755.0392	1305600.0000	46
47	428755.0392	1305630.0000	47
48	428755.0392	1305660.0000	48
49	428755.0392	1305690.0000	49
50	428755.0392	1305720.0000	50
51	428755.0392	1305750.0000	51
52	428755.0392	1305780.0000	52
53	428755.0392	1305810.0000	53
54	428755.0392	1305840.0000	54
55	428755.0392	1305870.0000	55
56	428755.0392	1305900.0000	56
57	428755.0392	1305930.0000	57
58	428755.0392	1305960.0000	58
59	428755.0392	1305990.0000	59
60	428755.0392	1306020.0000	60
61	428755.0392	1306050.0000	61
62	428755.0392	1306080.0000	62
63	428755.0392	1306110.0000	63
64	428755.0392	1306140.0000	64
65	428755.0392	1306170.0000	65
66	428755.0392	1306200.0000	66

Координаты Красных Линий			
Часть 4			
№	X	Y	№
1	428755.0392	1305220.0000	1
2	428755.0392	1305250.0000	2
3	428755.0392	1305280.0000	3
4	428755.0392	1305310.0000	4
5	428755.0392	1305340.0000	5
6	428755.0392	1305370.0000	6
7	428755.0392	1305400.0000	7
8	428755.0392	1305430.0000	8
9	428755.0392	1305460.0000	9
10	428755.0392	1305490.0000	10
11	428755.0392	1305520.0000	11
12	428755.0392	1305550.0000	12
13	428755.0392	1305580.0000	13
14	428755.0392	1305610.0000	14
15	428755.0392	1305640.0000	15
16	428755.0392	1305670.0000	16
17	428755.0392	1305700.0000	17
18	428755.0392	1305730.0000	18
19	428755.0392	1305760.0000	19
20	428755.0392	1305790.0000	20
21	428755.0392	1305820.0000	21
22	428755.0392	1305850.0000	22
23	428755.0392	1305880.0000	23
24	428755.0392	1305910.0000	24
25	428755.0392	1305940.0000	25
26	428755.0392	1305970.0000	26
27	428755.0392	1306000.0000	27
28	428755.0392	1306030.0000	28
29	428755.0392	1306060.0000	29
30	428755.0392	1306090.0000	30
31	428755.0392	1306120.0000	31
32	428755.0392	1306150.0000	32
33	428755.0392	1306180.0000	33
34	428755.0392	1306210.0000	34
35	428755.0392	1306240.0000	35
36	428755.0392	1306270.0000	36
37	428755.0392	1306300.0000	37
38	428755.0392	1306330.0000	38
39	428755.0392	1306360.0000	39
40	428755.0392	1306390.0000	40
41	428755.0392	1306420.0000	41
42	428755.0392	1306450.0000	42
43	428755.0392	1306480.0000	43
44	428755.0392	1306510.0000	44
45	428755.0392	1306540.0000	45
46	428755.0392	1306570.0000	46
47	428755.0392	1306600.0000	47
48	428755.0392	1306630.0000	48
49	428755.0392	1306660.0000	49
50	428755.0392	1306690.0000	50
51	428755.0392	1306720.0000	51
52	428755.0392	1306750.0000	52
53	428755.0392	1306780.0000	53
54	428755.0392	1306810.0000	54
55	428755.0392	1306840.0000	55
56	428755.0392	1306870.0000	56
57	428755.0392	1306900.0000	57
58	428755.0392	1306930.0000	58
59	428755.0392	1306960.0000	59
60	428755.0392	1306990.0000	60
61	428755.0392	1307020.0000	61
62	428755.0392	1307050.0000	62
63	428755.0392	1307080.0000	63
64	428755.0392	1307110.0000	64
65	428755.0392	1307140.0000	65
66	428755.0392	1307170.0000	66

Координаты Красных Линий			
Часть 5			
№	X	Y	№
1	428755.0392	1305220.0000	1
2	428755.0392	1305250.0000	2
3	428755.0392	1305280.0000	3
4	428755.0392	1305310.0000	4
5	428755.0392	1305340.0000	5
6	428755.0392	1305370.0000	6
7	428755.0392	1305400.0000	7
8	428755.0392	1305430.0000	8
9	428755.0392	1305460.0000	9
10	428755.0392	1305490.0000	10
11	428755.0392	1305520.0000	11
12	428755.0392	1305550.0000	12
13	428755.0392	1305580.0000	13
14	428755.0392	1305610.0000	14
15	428755.0392	1305640.0000	15
16	428755.0392	1305670.0000	16
17	428755.0392	1305700.0000	17
18	428755.0392	1305730.0000	18
19	428755.0392	1305760.0000	19
20	428755.0392	1305790.0000	20
21	428755.0392	1305820.0000	21
22	428755.0392	1305850.0000	22
23	428755.0392	1305880.0000	23
24	428755.0392	1305910.0000	24
25	428755.0392	1305940.0000	25
26	428755.0392	1305970.0000	26
27	428755.0392	1306000.0000	27
28	428755.0392	1306030.0000	28</