



Координаты Красных Линий
Часть 2

№	X	Y
1	429316.2900	1303936.0900
2	429376.5800	1303998.1700
3	429472.7200	1304179.1500
4	429459.5700	1304230.2500
5	429501.3400	1304261.5800
6	429465.9977	1304264.0577
7	429453.3300	1304406.6400
8	429447.3900	1304417.9900
9	429441.0700	1304436.1900
10	429429.6300	1304469.2400
11	429422.6500	1304489.3800
12	429402.8753	1304556.3923
13	429389.8860	1304576.2599
14	429257.0000	1304709.9500
15	429244.9200	1304722.8300
16	429191.4700	1304790.4300
17	429175.0200	1304797.3300
18	429096.8600	1304880.5800
19	429072.5600	1304894.2500
20	429044.6400	1304901.0000

Координаты Красных Линий
Часть 3

№	X	Y
1	428972.4499	1304800.6699
2	428974.2599	1304804.8599
3	428978.2299	1304836.5999
4	428979.5107	1304865.9097
5	429000.3261	1304907.8575
6	428963.3961	1304926.9560
7	428974.5398	1304766.4445
8	428857.6389	1305057.8019
9	428787.2889	1305101.5867
10	428713.3200	1305138.0500
11	428676.6400	1305131.2500
12	428613.1900	1305040.0400
13	428645.5100	1305013.3400
14	428782.5900	1304900.0600
15	428829.5900	1304861.2100
16	428908.9898	1304538.2900
17	428823.0800	1304836.7600
18	428826.0300	1304828.3400
19	428841.0400	1304810.8200
20	428862.5900	1304806.6000
21	428895.6700	1304788.9800
22	428925.8500	1304768.3400
23	428951.2400	1304751.6800

Координаты Красных Линий
Часть 4

№	X	Y
1	428540.5500	1304534.1500
2	428649.7800	1304534.6700
3	428634.2100	1304534.2100
4	428649.0300	1304460.8300
5	428419.0300	1304460.8300
6	428419.0300	1304270.4300
7	428399.4100	1304270.5700
8	428399.4100	1304179.0100
9	428399.8156	1304203.0862
10	428424.1034	1305076.9430
11	428432.7700	1305076.4200
12	428452.2400	1305076.0600
13	428583.6500	1305073.6100
14	428589.7100	1305195.7800
15	428615.2873	1304837.9404
16	428620.0473	1305227.2956

Координаты Красных Линий
Часть 5

№	X	Y
1	428668.6341	1304089.0730
2	428679.9265	1304095.1936
3	428693.6257	1304104.2790
4	428703.6880	1304104.8809
5	428706.0441	1304108.9820
6	428733.4542	1304111.7131
7	428751.5749	1304113.2866
8	428768.4700	1304113.2500
9	428775.0470	1304112.2070
10	428781.2642	1304116.3122
11	428859.6854	1304089.5693
12	428868.3156	1304083.1882
13	428530.9500	1305043.7300
14	428519.1600	1305045.7200
15	428514.3800	1305042.3400
16	428510.7900	1305038.8000
17	428510.7900	1305038.8000
18	428510.7900	1305038.8000
19	428510.7900	1305038.8000
20	428510.7900	1305038.8000
21	428510.7900	1305038.8000
22	428510.7900	1305038.8000
23	428510.7900	1305038.8000
24	428510.7900	1305038.8000
25	428510.7900	1305038.8000
26	428510.7900	1305038.8000
27	428510.7900	1305038.8000
28	428510.7900	1305038.8000
29	428510.7900	1305038.8000
30	428510.7900	1305038.8000

Координаты Красных Линий
Часть 6

№	X	Y
1	428678.0000	1304532.0800
2	428680.4400	1304842.3100
3	428716.0000	1304566.2300
4	428788.2340	1304832.6086
5	428791.5321	1304837.5829
6	428797.7542	1304845.4233
7	428806.1084	1304851.6589
8	428807.9010	1304857.9330
9	428804.7640	1304863.3108
10	428597.0756	1305036.7458
11	428581.2051	1305033.4926
12	428581.2051	1305033.4926
13	428581.2051	1305033.4926
14	428581.2051	1305033.4926
15	428581.2051	1305033.4926
16	428581.2051	1305033.4926
17	428581.2051	1305033.4926
18	428581.2051	1305033.4926
19	428581.2051	1305033.4926
20	428581.2051	1305033.4926
21	428581.2051	1305033.4926
22	428581.2051	1305033.4926
23	428581.2051	1305033.4926
24	428581.2051	1305033.4926
25	428581.2051	1305033.4926
26	428581.2051	1305033.4926
27	428581.2051	1305033.4926
28	428581.2051	1305033.4926
29	428581.2051	1305033.4926
30	428581.2051	1305033.4926

Координаты Красных Линий
Часть 7

№	X	Y
1	428735.7019	1304448.9834
2	428729.2747	1304496.8743
3	428723.8712	1304490.8407
4	428721.1276	1304449.4900
5	428718.6988	1304505.4500
6	428718.6988	1304505.4500
7	428718.6988	1304505.4500
8	428718.6988	1304505.4500
9	428718.6988	1304505.4500
10	428718.6988	1304505.4500
11	428718.6988	1304505.4500
12	428718.6988	1304505.4500
13	428718.6988	1304505.4500
14	428718.6988	1304505.4500
15	428718.6988	1304505.4500
16	428718.6988	1304505.4500
17	428718.6988	1304505.4500
18	428718.6988	1304505.4500
19	428718.6988	1304505.4500
20	428718.6988	1304505.4500

Координаты Красных Линий
Часть 8

№	X	Y
1	428735.7019	1304448.9834
2	428729.2747	1304496.8743
3	428723.8712	1304490.8407
4	428721.1276	1304449.4900
5	428718.6988	1304505.4500
6	428718.6988	1304505.4500
7	428718.6988	1304505.4500
8	428718.6988	1304505.4500
9	428718.6988	1304505.4500
10	428718.6988	1304505.4500
11	428718.6988	1304505.4500
12	428718.6988	1304505.4500
13	428718.6988	1304505.4500
14	428718.6988	1304505.4500
15	428718.6988	1304505.4500
16	428718.6988	1304505.4500
17	428718.6988	1304505.4500
18	428718.6988	1304505.4500
19	428718.6988	1304505.4500
20	428718.6988	1304505.4500

Координаты Красных Линий
Часть 9

№	X	Y
1	428735.7019	1304448.9834
2	428729.2747	1304496.8743
3	428723.8712	1304490.8407
4	428721.1276	1304449.4900
5	428718.6988	1304505.4500
6	428718.6988	1304505.4500
7	428718.6988	1304505.4500
8	428718.6988	1304505.4500
9	428718.6988	1304505.4500
10	428718.6988	1304505.4500
11	428718.6988	1304505.4500
12	428718.6988	1304505.4500
13	428718.6988	1304505.4500
14	428718.6988	1304505.4500
15	428718.6988	1304505.4500
16	428718.6988	1304505.4500
17	428718.6988	1304505.4500
18	428718.6988	1304505.4500
19	428718.6988	1304505.4500
20	428718.6988	1304505.4500

Координаты Красных Линий
Часть 10

№	X	Y
1	427953.2100	1305133.1200
2	428028.6800	1305146.4600
3	428039.3500	1305148.3100
4	428036.1000	1305157.9000
5	428036.1000	1305157.9000
6	428036.1000	1305157.9000
7	428036.1000	1305157.9000
8	428036.1000	1305157.9000
9	428036.1000	1305157.9000
10	428036.1000	1305157.9000
11	428036.1000	1305157.9000
12	428036.1000	1305157.9000
13	428036.1000	1305157.9000
14	428036.1000	1305157.9000
15	428036.1000	1305157.9000
16	428036.1000	1305157.9000
17	428036.1000	1305157.9000
18	428036.1000	1305157.9000
19	428036.1000	1305157.9000
20	428036.1000	1305157.9000

Координаты Красных Линий
Часть 11

№	X	Y
1	427953.2100	1305133.1200
2	428028.6800	1305146.4600
3	428039.3500	1305148.3100
4	428036.1000	1305157.9000
5	428036.1000	1305157.9000
6	428036.1000	1305157.9000
7	428036.1000	1305157.9000
8	428036.1000	1305157.9000
9	428036.1000	1305157.9000
10	428036.1000	1305157.9000
11	428036.1000	1305157.9000
12	428036.1000	1305157.9000
13	428036.1000	1305157.9000
14	428036.1000	1305157.9000
15	428036.1000	1305157.9000
16	428036.1000	1305157.9000
17	428036.1000	1305157.9000
18	428036.1000	1305157.9000
19	428036.1000	1305157.9000
20	428036.1000	1305157.9000

Координаты Красных Линий
Часть 12

№	X	Y
1	427953.2100	1305133.1200
2	428028.6800	1305146.4600
3	428039.3500	1305148.3100
4	428036.1000	1305157.9000
5	428036.1000	1305157.9000
6	428036.1000	1305157.9000
7	428036.1000	1305157.9000
8	428036.1000	1305157.9000
9	428036.1000	1305157.9000
10	428036.1000	1305157.9000
11	428036.1000	1305157.9000
12	428036.1000	1305157.9000
13	428036.1000	1305157.9000
14	428036.1000	1305157.9000
15	428036.1000	1305157.9000
16	428036.1000	1305157.9000
17	428036.1000	1305157.9000
18	428036.1000	1305157.9000
19	428036.1000	1305157.9000
20	428036.1000	1305157.9000

Координаты Красных Линий
Часть 13

№	X	Y
1	427953.2100	1305133.1200
2	428028.6800	1305146.4600
3	428039.3500	1305148.3100
4	428036.1000	1305157.9000
5	428036.1000	1305157.9000
6	428036.1000	1305157.9000
7	428036.1000	1305157.9000
8	428036.1000	1305157.9000
9	428036.1000	1305157.9000
10	428036.1000	1305157.9000
11	428036.1000	1305157.9000
12	428036.1000	1305157.9000
13	428036.1000	1305157.9000
14	428036.1000	1305157.9000
15	428036.1000	1305157.9000
16	428036.1000	1305157.9000
17	428036.1000	1305157.9000
18	428036.1000	1305157.9000
19		